AMENDMENTS TO THE DRAWINGS

The drawings were objected to as failing to comply with 37 C.F.R. 1.84(p)(4) because reference character, for example, "24" of Figure 1 and Figure 6 has been used to designate both motor and printer. In response, the motor in Figure 6 has been renumbered 18.

The drawings were objected to as failing to comply with 37 C.F.R. 1.84(p)(5) because they do not include the following reference sign(s) mentioned in the description: for example, roller 18, substrate 14 of page 5, transfer assist apparatus 50 of page 6, specification, is not shown in Figure 6. In response, roller 18 has been renumbered 20 with appropriate changes in the specification, and substrate 14 has been labeled in Figure 6. The text on page 6 now makes clear that a transfer assist apparatus is not shown in Figure 6.



1/6

